

Building Safety Certificate

No:

Dated:

It is certified that the existing building Chapter EM School at Bandar Kota Rd. Machilipatnam, Krishna District, Andhra Pradesh 521003 is having block(s)/ floor(s) as per details below:

Detail of block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+4					

The building is occupied/ owned by Chapter EM School have complied with the building safety requirements in accordance with National Building Code rules and verified by the officers concerning R&B Department on 21.08.2024 (date of inspection) in the presence of M. Manoj, Manager, Chapter EM School, Machilipatnam, Krishna District, AP, 521003, and that the building/premises is fit for occupancy for running school with effect from immediate for a period of 02(Two) years in accordance with rule and subject to complaints of the specific conditions as appended.

1. NONE
2. NONE
3. NONE
4. NONE

Issued on 21.08.2024 at Machilipatnam by R&B Authorities

Strikeout whichever is not applicable. In case of block is more than six use separate sheet for detail

Signature will seal:

Name:

Designation:

Name and address of department/Office:

(T. SANGEETHA) 21/08/24

Deputy Executive Engineer
(R & B) Machilipatnam

M. Sujin
PRINCIPAL
CHAPTER (EM) SCHOOL
BANDARKOTA ROAD,
MACHILIPATNAM - 521 001